



Preliminary Information

PIP5862 Diagnostic Tip: DTC P0442

Proactive

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Encore	2021 - 2022	All	All	1.4 LE2	All
Chevrolet	Trax	2021 - 2022	All	All	1.4 LE2	All

Involved Region or Country:	North America
Condition:	DTC P0442
Cause:	Complete published diagnostics for DTC P0442 and leak test Evaporative Emission System as directed

Correction

When diagnosing DTC p0442 please complete the published SI diagnostics and perform the evap. system leak testing as directed. If no issues can be isolated then replace the Evaporative Emissions Canister and evaluate.

Note: Purge solenoids and Purge Pumps returned for warranty part analysis have been tested with no problems found.

This PI will become a bulletin once additional information becomes available.

Version History

Version	1
Modified	07/28/2022 - Created on.

