



## STAR ONLINE PUBLICATION



---

**Case Number:** S2124000013

**Release Date:** Aug 2021

**Symptom/Vehicle Issue:** Vehicle Sets DTC P0480 Cooling Fan 1 Control Circuit

**Customer Complaint/Technician Observation:** Vehicle Has DTC P0480 Cooling Fan 1 Control Circuit Fault Code.

**Discussion:** This condition is for NMB (Standard Duty) vehicles only. There is a TSB being created for this condition with updated parts to correct the fault code. The correct fan can be isolated by looking at the connectors show below. If there is Green/Blue mark present on the connector than standard diagnostics can be performed. If the mark is not present on the connector the fan needs to be replaced with most updated part number available in STAR Parts.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**