

GPOP - Issue Review System

Part Number: 56029400A\$, 68241067A\$, 68406529A\$

Part Description: SENSOR, Tire Pressure

Issue If replacing parts due to C1501-96, C1502-96, C1503-96, or C1504-96, contact FCA
Description: Redacted Content prior to repair.

If no response within 15 minutes, proceed with repair.

Please document concern, diagnosis and correction well on repair order or for a possible follow-up call to clearly understand the issue.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.