



STAR ONLINE PUBLICATION



Case Number: S2108000042

Release Date: 02/12/2021

Symptom/Vehicle Issue: MIL Malfunction Indicator Lamp On, DTC P0198 Oil Temperature Sensor Circuit High

Customer Complaint/Technician Observation: Owner complains the MIL warning lamp is on. Technician observed, DTC P0198 Oil Temperature Sensor Circuit High stored or active.

Repair Procedure: Inspect the harness routing for the oil temperature sensor. Repair and reposition the harness at the suspect location as needed Fig 1,2,3.




Fig 1

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.


Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found



STAR ONLINE PUBLICATION



Contact area



Location view from Underbody




Fig 2

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found



STAR ONLINE PUBLICATION



Reposition after repairs.

Connector repair kit
68064995AA




Fig 3

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found