



STAR ONLINE PUBLICATION



Case Number: S1508000323 REV. A

Release Date: 03/06/2021

Symptom/Vehicle Issue: PCM Sets DTC P1400-Aftermarket Calibration Detected/Warranty Coverage Confirmation Required

Discussion: When installing a Scat Pack 1 Performance Package, the P1400-Aftermarket Calibration Detected/Warranty Coverage Confirmation Required DTC as a stored fault. The P1400 PCM DTC cannot be cleared with the performance package installed. The DTC does not affect the performance of the vehicle; do not replace any parts. Mopar Performance 888-528-4364.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found