



STAR ONLINE PUBLICATION




Case Number: S2108000072

Release Date: 03/17/2021

Symptom/Vehicle Issue: MIL (Malfunction Indicator Lamp) On, DTC P0073 Ambient Air Temperature Sensor Circuit High, B1029-12 External Temperature Sensor-Circuit Short To Battery

Customer Complaint/Technician Observation: Owner complaint, MIL lamp on. Technician observed DTC P0073 Ambient Air Temperature Sensor Circuit High, B1029-12 External Temperature Sensor- Circuit Short To Battery.

Repair Procedure: Inspect I154A, the A pillar door connector, for signs of corrosion, TPO (terminals pushed out), bent or spread terminals. Clean and secure as needed no parts required.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found