

GPOP - Issue Review System

Part Number: 68518243a\$, 05149265A\$

Part Description: Ambient Temp Sensor

Issue PSU- Pentastar Upgrade Engine - Ambient Temp Sensors

Description: After experiencing any P0070-11, P0070-15, P0071, P0072, or P0073 codes, follow the diagnostic procedure. If the procedure directs you to replace the ambient air temp sensor, then please call FCA Redacted Content before replacing the part. If no answer in 15 minutes, proceed with repair.
