

GPOP - Issue Review System

Part Number: 68399001A\$, 68434538A\$, 68434916A\$, 68193711A\$

Part Description: Fuel Pump Control Module, PCM, and Fuel Pump Module

Issue Description: Do not replace the PCM, Fuel Pump Control Module, or Fuel Pump Module for a P062A DTC. Please email FCA Redacted Content with your contact information and provide a vehicle scan report from WiTECH showing the DTC in Active, Pending, or Stored status. If no response in 15 minutes, proceed with repair.