

Subject

MIL ON P043E00, P043F00, P24007E, P24007F, P24187E

Market

USA

Service Category

Engine/Hybrid System

Section

Emission Control

Applicability

NAP Vehicles with A25A-FKS/FXS engines
APPLICABLE VEHICLES

2019-2022	Avalon HV	2020-2022	Highlander HV
2019-2022	RAV4	2018-2022	Camry
2019-2022	RAV4 HV	2018-2022	Camry HV
2021-2022	Sienna HV		

CONDITION

Some Model Year 2018-2022 vehicles equipped with A25A-FKS or A25A-FXS engines may experience a MIL ON condition with the following DTCs: P043F00, P043E00, P24007E, P24007F, P24187E.

RECOMMENDATIONS

This condition is currently under investigation. Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

LINK REFERENCES

This Tech Tip does not contain any link references