



Preliminary Information

PIT5948A Service Trailer Brake Message With DTC C159C

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade Models	2022	6/10/2022	EOP	All	All
Chevrolet	Silverado 1500 New (RPO J22, VIN Digit 5 = A or D)	2022 - 2023	11th VIN Digit Z: 7/12/2022, G: 6/30/2022, or 1: 6/27/2022	9/29/2022	All	All
Chevrolet	Suburban	2022	6/10/2022	EOP	All	All
Chevrolet	Tahoe	2022 - 2023	6/10/2022	EOP	All	All
GMC	Sierra 1500 New (RPO J22, VIN Digit 5 = H or U)	2022 - 2023	11th VIN Digit Z: 7/12/2022, G: 6/30/2022, or 1: 6/27/2022	9/29/2022	All	All
GMC	Yukon Models	2022	6/10/2022	EOP	All	All

Involved Region or Country	North America
Additional Options (RPO)	RPO JL1
Condition	Some customers may comment when a trailer is connected to the truck that there is a Service Trailer Brake message displayed in the DIC. When checking for DTCs, a C159C sym49 maybe set for the Trailer Brake Control Switch. This condition could be intermittent, and when the fault is present the electric trailer brake functions will not be operational for that key cycle.
Cause	Unknown

Correction:

GM Engineering is aware of the issue and working on a fix. When more information is available this PI will be updated.

Version History

Version	2
Modified	09/27/2022 - Created on. 10/06/2022 - Updates to Model List and Condition sections



GENERAL MOTORS

© 2022 General Motors. All Rights Reserved.