



STAR ONLINE PUBLICATION



Case Number: S2208000169

Release Date: October 2022

Symptom/Vehicle Issue: RFH Has Stored B1A7D-01 Start Button – General Electrical Failure

Diagnosis: When scanning the vehicle for DTC's you may find B1A7D-01 Start Button – General Electrical Failure STORED in the RFH. If there are no customer related symptoms, it's likely the B1A7D-01 is falsely setting.

Repair Procedure: Neither the KIN or RFH module should be replaced. A software update for the RFH addressing the falsely setting B1A7D-01 will be released mid 4th quarter 2022.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found