

Subject

MIL On P26CA12, P26CA14, P26CB71, P26CA31, P26CE37

Market

USA

Service Category

Engine/Hybrid System

Section

Cooling

Applicability

MY2022-2023 A25A-FKS & A25A-FXS

APPLICABLE VEHICLES

2022	Avalon HV	2022-2023	Venza HV
2022-2023	Highlander HV	2022-2023	RAV4
2022-2023	Camry	2022-2023	RAV4 HV
2022-2023	Camry HV	2022-2023	Sienna HV

CONDITION

Some MY2022-2023 vehicles equipped with A25A-FKS or A25A-FXS engines may experience a MIL on condition with one or more of the following DTCs: P26CA12, P26CA14, P26CB71, P26CA31, P26CE37.

RECOMMENDATIONS

Please create a TAS case and contact TAS for further instructions prior to diagnosis or repairing of the vehicle. If it is a weekend or holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

LINK REFERENCES

This Tech Tip does not contain any link references