

9100115

12/16/2022

MY 21-23 JL

GPOP - Issue Review System

Part Number: 05185035A\$,

Part Description: Integrated Dual Charging Module

Issue Before replacing the IDCM part please follow the appropriate service procedure for DTC P0D27, ensure to clear the codes
Description: and perform a charging test. If the codes come back again, proceed with the replacement.