

GPOP - Issue Review System

Part Number: 68438679A\$, 68423754A\$

Part Description: GRILLE, Active Shutter

Issue Description: For a Customer Concern of Check Engine Light On and DTC U11E9- PCM Lost Communication with Active Grille Shutter (AGS) is set, please review Star Online S2008000132 for known concerns. Prior to replacing this part please call FCA Redacted Content.

If no response in 15 minutes, please proceed with repair.

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
