

9100116

01/06/2023

MY 21-23 JL

GPOP - Issue Review System

Part Number: 68443442A\$,

Part Description: Valve - Coolant

Issue JL PHEV Hoses to 3-Way valve coolant hoses misroute causes P0E80-00. Check hose routing as outlined in Star Online
Description: Publication S2208000205 or on a known good vehicle before replacing valve. Routing hoses correctly will likely fix the issue.