



Preliminary Information

PIT5949B Overhead Roof Console Inoperative / Service Safety Restraints Message / Sunroof Inoperative / Dome Lights Inoperative / DTCs B1A7A and U1121

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade Models	2021 - 2023	All	All	All	All
Chevrolet	Suburban	2021 - 2023	All	All	All	All
Chevrolet	Tahoe	2021 - 2023	All	All	All	All
GMC	Yukon Models	2021 - 2023	All	All	All	All

Involved Region or Country	North America
Condition	In some rare cases, a customer may comment at start up that their vehicle has the following symptoms: - Service Safety Restraints System Message - Sunroof Inoperative - Sunshade Lights Inoperative - Dome Lights Inoperative - Power Liftgate Inoperative when using switch in overhead console - DTCs U1121 set in the BCM and B1A7A set in the Restraints Module During the condition, if one of the overhead roof console dome/map lights is cycled on/off then all functions will return to normal operation for the entire ignition cycle. Important: Even when all other overhead roof console functions are inoperative, the Onstar button / LED will still be operational. Note: For the 2021 model year vehicles, please be aware of PIT5774F which has a similar condition, but the conditions listed in that PI do not recover functionality if the dome/map light switch is cycled on/off.
Cause	Unknown

Correction:

GM Engineering is working on a fix. In the meantime, if this condition occurs please ask the customer to cycle one of the overhead roof console dome/map lights on/off. This will correct the concerns for that ignition cycle.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage

information.

Labor Operation	Description	Labor Time
6086038	Interior Overhead Systems - Fix in Progress	0.2 Hr

Version History

Version	3
Modified	09/27/2022 - Created on. 01/25/2023 - Updates to the Warranty Section 04/04/2023 - Updates to the Warranty Section



© 2023 General Motors. All Rights Reserved.