



Preliminary Information

PIP5917 2024 6.6L L5P Setting DTC P0422

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2500/3500HD	2024	All	All	6.6L L5P	All
GMC	Sierra 2500/3500HD	2024	All	All	6.6L L5P	All

Region:	North America
Condition:	Customer may complain of a MIL on the DIC
Cause:	A technician may find DTC P0422 set in the ECM

Correction:

If the vehicle has less than 1500 miles and this is the first occurrence of only P0422 set, please clear the code and return the vehicle to the customer.

If the vehicle has more than 1500 miles or vehicle has been in for this code previously, please follow the diagnostics in SI.

Version History

Version	1
Modified	04/25/2024 - Created on.

