

GPOP - Issue Review System

Part Number: 04672800A\$, 68609627A\$

Part Description: Long Range Camera Front

Issue Description: For concern of Central ADAS Decision Module (CADM) setting C2318-49 - Front Camera Internal Electronic Failure and P0602-00 - Control Module Programming Error/Not Programmed, some recently replaced windshield Long Range Front Cameras (LRCF) and CADM(s) have been found with no problems after testing. Prior to replacing the camera, Please Contact FCA Redacted Content. If no response in 15 minutes, please proceed with repair.