

SSM 51677

2021-2023 Bronco - Ambient Air Temperature (AAT) Inaccurate With Diagnostic Trouble Code (DTC) P0072 - Workshop Manual Updates

Some 2021-2023 Bronco vehicles may exhibit an inaccurate AAT reading with DTC P0072 stored in the powertrain control module (PCM). The Workshop Manual (WSM), Section 413-01 > pinpoint test (PPT) BC has been updated to address this concern. The AAT WSM updates include: improved diagnosis and testing, AAT sensor reset, and the AAT sensor interaction with climate control system and gateway module A (GWM).