

SSM 51761

2022-2023 F-150 Lightning - Illuminated Malfunction Indicator Lamp (MIL) With Diagnostic Trouble Code P0A3C:94 In The SOBDMB And/Or SOBDMC

Some 2022-2023 F-150 Lightning vehicles may exhibit diagnostic trouble code P0A3C:94 stored in either the secondary on-board diagnostic control module B (SOBDMB) and/or secondary on-board diagnostic control module C (SOBDMC). This may be due to the software within either the SOBDMB and/or SOBDMC. Engineering is currently working on a solution that is expected in November 2023. Inform the customer they can continue to drive the vehicle. Monitor OASIS for additional updates.