

SSM 51706

2023 Bronco- Illuminated malfunction indicator lamp (MIL) with diagnostic trouble code (DTC) P051B stored in the powertrain control module (PCM)

Some 2023 Bronco vehicles equipped with a 2.7L engine may exhibit an illuminated malfunction indicator lamp (MIL) with diagnostic trouble code (DTC) P051B stored in the powertrain control module (PCM). PCM software is currently under development to resolve this condition and is scheduled to be available by 30-Jun-2023. Monitor OASIS for updates and schedule a follow up with the customer when the software becomes available