



Preliminary Information

PIC6510 U110D SYM00

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	LYRIQ	2024	All	All	All	All

Involved Region or Country	North America
Condition	A U110D may be found setting current with no interior lamps being inoperable.
Cause	Under Investigation

Correction:

Engineering is aware of the concern and is working on a resolution.

IF U110D is found setting current with no Interior Lamp faults, do not attempt a repair or replace any parts.

This PI will be converted to a Bulletin when a resolution is available.

Version History

Version	1
Modified	06/29/2023 - Created on.

