

GPOP - Issue Review System

Part Number: 68588637A\$, 68588639A\$, 68588643A\$, 68588647A\$, 68598819A\$,
68611543A\$

Part Description: Occupant Restraint Controller

Issue Description: For concern of DTC B767-49 Left Impact Pressure Sensor-Internal Failure OR DTC B2768-49 Right Impact Pressure Sensor-Internal Failure, prior to replacement of any components please contact engineering at FCA Redacted Content for further assistance. If no response in 15 minutes, proceed with repair.