

## GPOP - Issue Review System

**Part Number:** 68588637A\$, 68588639A\$, 68588643A\$, 68588647A\$,  
68598819A\$, 68611543A\$

**Part Description:** Occupant Restraint Controller

**Issue** For concern of DTC B2767-49 Left Impact Pressure Sensor-Internal Failure OR DTC  
**Description:** B2768-49 Right Impact Pressure Sensor-Internal Failure, prior to replacement of any  
components please contact FCA Redacted Content for further assistance. If no  
response in 15 minutes, proceed with repair.