

SSM 51828 2021-2023 F-150 - Inoperative Windshield Wiper Motor With DTCs B130F:12, B130F:14, And/Or B1131:02

Some 2021-2023 F-150 vehicles may exhibit an inoperative windshield wiper motor condition with diagnostic trouble codes (DTCs) B130F:12 and/or B130F:14 stored in the body control module (BCM), and/or B1131:02 stored in the steering column control module (SCCM). This may be due to the connection at the windshield wiper motor connector. Refer to the Wiring Diagram, Cell 150 - Connector Views, C125 (Windshield Wiper Motor). Workshop Manual (WSM), Section 501-16, Wipers and Washers, Diagnosis and Testing, Pinpoint Test A has recently been updated to provide new direction for this diagnosis. Refer to the WSM, Section 501-16, Wipers and Washers, Diagnosis and Testing, Pinpoint Test A for applicable diagnosis.