

9100191

07/19/2023

MY21 WL

GPOP - Issue Review System

Part Number: 68373970A\$

Part Description: SHAFT, Front Axle Output

Issue Description: For concerns related to a C1463-94 OR C1472-92 DTC, reference the latest version of TSB 08-103-22 prior to replacing the Front Axle Disconnect (FAD) / Output Shaft. If DTCM software update does not resolve concern proceed with repair.