

GPOP - Issue Review System

Part Number: 68585099a\$, 68585100a\$, 68585101a\$, 68585102a\$, 68585103a\$,
68585104a\$, 68585105a\$

Part Description: EPS Steering Gear

Issue Description: Prior to replacing EPS gear for Can C Bus Diagnostic Trouble Codes (DTCs), U0001 & U0002, please contact FCA Redacted Content.

Please have the following info available:

VIN, vehicle complaint, diagnostics completed, first name and last name, Dealer code, Service Manager name, Phone number or email address.

If no response received in 15 minutes, proceed with part repair.