

GPOP - Issue Review System

Part Number: 05013470A\$, 52109082A\$, 52119671A\$, R8419671A\$, R8448028A\$,
R8450973A\$, RL419671A\$

Part Description: Pump Assy and Reaction Shaft

Issue Description: 2023 DJ & D2: If DTCs P0944 and P0868 are present, do not replace the torque converter or internal transmission components. Refer to SOL Publication S2321000007.