

Service Alert

Mazda North American Operations
Irvine, CA 92618-2922

**Subject:**

DTC P2BF5, P2BF6 & P2BF7

Service Alert No.: SA-056/23

Last Issued : 09/28/2023

BULLETIN NOTES**APPLICABLE MODEL(S)/VINS:**

2024 CX-5

DESCRIPTION

Permanent updates to these procedures in the WSM are in progress and once complete this Service Alert will be unpublished. While these updates are being completed please see the procedures for DTC's P2BF5, P2BF6 and P2BF7 below.

- P2BF5
- P2BF6
- P2BF7

Page 1 of 1

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.