



Technical Service Bulletin

55 gesture-controlled rear lid not working, B13034A

55 23 80 2067818/2 October 16, 2023. Supersedes Technical Service Bulletin Group 55 number 22-71 dated August 18, 2022, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A4 allroad, S4, A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, RS 5, RS 5 Sportback, A6, A6 allroad, S6, RS 6 Avant, A7, S7, RS 7, A8, S8, e-tron GT, and RS e-tron GT	2023 – 2025	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Added Model Year 24 and 25) Revised <i>Technical Background</i> (added PR number) Revised <i>Service</i> (added PR number)
1	08/18/2022	Initial publication

Customer states:

The gesture-controlled rear lid is not working.

Workshop findings:

The following DTC may be stored:

- **B13034A**: Control module for rear lid opening, incorrect component installed in the Comfort System Central Control Module (address word 0046).
- Some early MY23 vehicles may have some components of the system installed (e.g. control unit or sensor).

Technical Background

This function has been discontinued from Model Year 2023 for this model (PR number BU2).



Technical Service Bulletin

Production Solution

Not applicable.

Service

- In regards to this model, as of model year 2023 (PR Number BU2) the gesture-controlled rear lid function is no longer available.
- Any related event memory entries which have been logged (refer to workshop findings) should be ignored.
- This feature cannot be enabled even if some of the parts of the system were installed at the factory.
- No work is required.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (**2067812**) are subject to change and/or removal.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.