



SSM 51992 2024 Mustang - Diagnostic Trouble Code C1018 Stored In The ABS Module

Some 2024 Mustang vehicles may exhibit a diagnostic trouble code (DTC) C1018 stored in the anti-lock brake system (ABS) module with no symptoms present. DTC C1018 should be ignored and no further service action is required. Replacement or reprogramming of the ABS module will not address this DTC.