



SSM 52003 2023-2024 F-Super Duty - Equipped With 360-Degree Camera And Blind Spot Monitoring With Trailing - DTCS U1020:00 And/Or U1036:00 Setting In The IPMA

Some 2023 F-Super Duty vehicles equipped with 360-degree camera and blind spot monitoring with trailing may exhibit diagnostic trouble codes (DTCS) U1020:00 And/Or U1036:00 in the image processing module A (IPMA) if the Ford accessories trailer blind spot information system (BLIS) has not been installed by the customer. If DTCs are present and trailer BLIS has not been installed per accessory kit instructions, they should be ignored as the IPMA is attempting to detect the trailer BLIS modules. No further service action is required.