



SSM 52018 2022 F-Super Duty - Blind Spot Monitoring System (BLIS®)/Cross Traffic Alert (CTA) - DTC B11D6:15

Some 2022 F-Super Duty vehicles equipped with BLIS®/CTA may exhibit fault messages with DTC B11D6:15 stored in the side obstacle detection control left/right (SODL/SODR) module. To correct the condition, replace the affected SODL/SODR module. Refer to Workshop Manual, Section 419-04. For claiming, use causal part 14C689.