

Subject

Fail to Restart After Start/Stop Event

Market

USA

Service Category

Engine/Hybrid System

Section

Engine Control

Applicability

Highlander/Grand Highlander/HV**APPLICABLE VEHICLES**

2023	Highlander	2024	Grand Highlander HV
2024	Grand Highlander		

CONDITION

Some MY23-24 Highlander and Grand Highlander/HV vehicles may experience a condition where the engine does not restart automatically following a start/stop event. However, the engine may be restarted normally after a period of time in the IG OFF condition. This condition typically sets DTC P154200. Please contact TAS for diagnostic instructions to aid in resolution of the condition.

RECOMMENDATIONS

Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or a holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

LINK REFERENCES

This Tech Tip does not contain any link references