



Bulletin No.: PIT6068A
Published date: 10/4/2023

Preliminary Information

PIT6068A Service Driver Assist B1A05

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Blazer EV	2024	All	All	All	All

Involved Region or Country	North America
Condition	Service driver assist message On inspection B1A05 will be found in the B174W Front View Camera Module (FVCM)
Cause	Software

Correction:

Reprogram B174W FVCM using SPS

Version History

Version	2
Modified	10/03/2023 - Created on. 10/04/2023 - Removed statement to learn FVC after programming per Bill Taylor, BQM.

