



# Preliminary Information

## PIC6527 U018B - Lost Communication with UHF Short Range Low Energy Remote Control Access Transceiver

### Models

| Brand:   | Model: | Model Years: | VIN: |     | Engine: | Transmissions: |
|----------|--------|--------------|------|-----|---------|----------------|
|          |        |              | from | to  |         |                |
| Cadillac | Lyriq  | 2023 - 2024  | All  | All | All     | All            |

|                            |                                                                     |
|----------------------------|---------------------------------------------------------------------|
| Involved Region or Country | North America                                                       |
| Condition                  | During diagnostics a U018B may be found setting current or history. |
| Cause                      | Calibration.                                                        |

### Correction:

The K183 UHF Short Range Low Energy Remote Control Access Transceiver is present but is not used on the 2023 and 2024 model year Cadillac Lyriq.

The Module is only present to complete the Can Bus.

Do not attempt to repair or diagnose a U018B, it will not cause any concerns with the vehicle.

### Version History

|          |                          |
|----------|--------------------------|
| Version  | 1                        |
| Modified | 11/01/2023 - Created on. |

