

GPOP - Issue Review System

Part Number: 68518243A\$

Part Description: Ambient Air Temperature Sensor

Issue Description: 2023-24MY RU Ambient Air Temperature Sensor not reading temp correctly or setting DTC P0073, P0070-15. Before ordering a new sensor, make sure to disconnect and connect sensor and drive vehicle for 5 minutes above 15 mph. Make sure there is no water into the sensor or harness connector. Please contact engineer FCA Redacted Content before replacing sensor. If no response in 15 minutes, proceed with repair.