

GPOP - Issue Review System

Part Number: 56029549A\$

Part Description: Dynamic Sensor

Issue Description: Prior to replacing this part, please ensure all the pre-diagnostic & diagnostic procedures have been completed with emphasis on wiring and connector integrity.

If codes C006A-28, U0125-00, or C006A-46 are present, warranty analysis suggests a high likelihood of an intermittent connection at or near the wiring connector, especially if the vehicle is a pursuit variant.

Please verify wiring per diagnostic procedures, as well as removal & installation guidance called out in the service manual before replacement.