

GPOP - Issue Review System

Part Number: 68524908A\$

Part Description: GEAR Rack And Pinion

Issue Description: IF VEHICLE BEING REPAIRED IS LISTED BELOW, ORDER 68624833AA. ALL OTHER APPLICATIONS ORDER 68524908AC

NOTE - 68524908AB does not supersede to 68524908AC for the following configurations, installing a 68524908AC will lead to a C2219 fault code.

WK:

3.6L/3.0L Gas 4x4, 5.7L V8/3.0L Diesel 4x2, SDA, SDZ, TDC, SDJ + 5YC + 5I8+ (EHW or ERC) + 5I4 + (SDA or SDJ or SDZ) + TDC OR 5YC + 5I8+ (EZH or EXF) + 5I2 + (SDA or SDJ or SDZ) + TDC

WK:

3.6L/3.0L Gas 4x4, 5.7L V8/3.0L Diesel 4x2, SDA, SDZ, TFB, SDJ+5YC + 5I8+ (EHW or ERC) + 5I4 + (SDA or SDJ or SDZ) + TFB OR 5YC + 5I8+ (EZH or EXF) + 5I2 + (SDA or SDJ or SDZ) + TFB

WK:

3.6L/3.0L Gas 4x4, 5.7L V8/3.0L Diesel 4x2, SDA, SDZ, TKJ, SDJ + 5YC + 5I8+ (EHW or ERC) + 5I4 + (SDA or SDJ or SDZ) + (TKJ or TLP) OR 5YC + 5I8+ (EZH or EXF) + 5I2 + (SDA or SDJ or SDZ) + TKJ

WK:

3.6L/3.0L Gas 4x4, 5.7L V8/3.0L Diesel 4x2, SDA, SDZ, TKN, SDJ+5YC + 5I8+ (EHW or ERC) + 5I4 + (SDA or SDJ or SDZ) + TKN OR 5YC + 5I8+ (EZH or EXF) + 5I2 + (SDA or SDJ or SDZ) + TKN

WD:

3.6L V6 4x4, 5.7L V8 4x2, SDA, SD2, TKJ5CW + 5I8+ ERC + 5I4 + (SDA or SD2) + TKJ OR 5CW + 5I8+ EZH + 5I2 + (SDA or SD2) + TKJ

WD:

3.6L V6 4x4, 5.7L V8 4x2, SDE, TKN 5CW + 5I8+ ERC + 5I4 + SDE + TKN OR 5CW + 5I8+ EZH + 5I2 + SDE + TKN