

Fault Code P063544 After Flashing or Initializing The Electrical Power Steering Control Unit

Topic number	LI46.35-P-077076
Version	1
Function group	46.35 - Electrical steering
Date	11/13/23
Validity	Model series 206, 214, 223, 236, 254, 294, 295, 296, 297, 232, 192
Reason for change	

Complaint

Control unit N68 - electric power steering

Fault P063544 - The electric power steering has a malfunction. There is a fault in the data memory.
with fault freeze frame data "Mon_ID 320" in the "stored" status stored in the fault memory of control unit N68.

No functional restrictions of the electric power steering or warning messages are visible.

Cause

Faults occur in the event of a software update or when initializing the control unit for the electric power steering N68.

Remedy

The fault code can be ignored and the fault memory of the control unit for the electric power steering N68 can be deleted.

It is not necessary to replace the electric power steering.

Symptoms				
Chassis/suspension > Steering system > Function > Parameter function				
Control unit/fault code				
Control unit		Fault text		
N68 - Electrical power steering (ES) (EPS223)		P063544 - The electric power steering has a malfunction. There is an error in the data memory.		
Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note

