

Subject: Engineering Information - Check Engine Lamp Illuminated on Driver Information Center (DIC), DTC's P0671, P0672, P0673, P0674, P0675 and P0676 Set

Attention: Proceed with this EI ONLY if the customer has commented about this concern AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard the PIE and proceed with diagnostics found in published service information. THIS IS NOT A RECALL refer to Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins.

This PI has been revised to end the need for gathering information from the field. Please discard PIE0760.

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2023	2024	—	—	Equipped with 3.0L	—
GMC	Sierra 1500						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	September 05, 2023 Revised December 22, 2023 - Ended the need for gathering further information from the field.