

GPOP - Issue Review System

Part Number: 68629572A\$

Part Description: Rear corner radar

Issue Description: Lost communication with right or left rear radar (U02B6/U02B7). Follow the procedure for the DTC. If the DTC is still active proceed with doing radar Pin Unlock and complete a radar swap. After doing a proper swap vehicle will need to be driven to calibrate. If the issue does not follow the radar, then proceed with changing wiring on the side that is causing the issue.