



STAR ONLINE PUBLICATION



Case Number: S2308000117

Release Date: September 2023

Symptom/Vehicle Issue: Check Engine Light On, P0CA6-00 Hybrid/EV Battery Charging Current High

Discussion: The customer may come in for a Check Engine Light. Upon scanning the vehicle for DTC's you may find P0CA6-00 Hybrid/EV Battery Charging Current High in the Battery Pack Control Module (BPCM).

Diagnosis: Perform the diagnostic flow chart for P0CA6-00. Checking related DTC's, high voltage wiring and connectors.

Repair: If the flow chart is inconclusive, the issue may be caused by BPCM software. A software update for the BPCM is scheduled to be released in early first quarter 2024.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found