

GPOP - Issue Review System

Part Number: 68670659A\$

Part Description: Radio Frequency Hub

Issue Symptom/Vehicle Issue:

Description: Remote Keyless Entry (RKE) And Remote Start Range Is Limited. B1A76-11 Remote Start Antenna Short To Ground Is Setting Erroneously. Please reference SOL S2308000145 before replacing the module. If you still feel that replacement is necessary please contact FCA REDACTED CONTENT before replacing the module. If no response within 15 minutes, proceed with repair.