

Audi On-car analysis list from March, 5 2024

Please contact Audi Helpline before attempting repair

All topics have associated worksheets to be filled out and attached to the TAC ticket. Worksheets can be found at: Elsa2Go>>Service References>> Search v4p

	Models	MY	Engine	Trans	Topic	Topic details
	Q3	2020-2021	All	All	Coolant warning Lamp	Customer states they receive a low coolant warning in the cluster. Coolant level appears to be full in the reservoir Case does not relate to TSB 2061918 Photo showing reservoir level
	A6, A7, Q8, Q7, S4, S5	2019-2023	3.0 EA839	All	Catalytic converter	P042000: Catalyst System,Bank1 Efficiency Below •FF Log with all fault codes and completed test plans. •IN-4-Pin Worksheet with answers to questions •Requested pictures, see Questions/ Steps in worksheet
	Q4 e-tron	2022-2024	All	All	Charging cable cannot be removed from the vehicle	See e-tron charging questionnaire worksheet
	Q3	2021-2024	all	all	P008700 - Low fuel pressure	MIL on with DTC P008700 Low fuel pressure Fill out worksheet Delivery rate test needed
	e-tron Q and SB Q8 e-tron and SB	2019-2024	All	All	Vehicle cannot be charged, charge socket lock without function	See e-tron charging questionnaire worksheet
	Q7, Q8	2017-2019	All	All	Corrosion on wheelhouse cover plate	2017-2019 Q7 2019 Q8 Various photos and inspections, see worksheet.
	e-tron GT	2022-2024	All	All	Front side window inoperative	Customer concern that a front door module function is inoperative water test, inspect door harness and pillar connection
	e-tron Quattro e-tron SB	2023-2024	Any	Any	Noise from Front Door Trim Panel	Noise from front door trim panel while driving Video of noise before repair is performed Photos of repair DTC P218500
	Q5	2022	Any	Any	Q5 Temp sensor	Various photos of surrounding area See worksheet
	A5	2023-2024	Any	Any	Noise from Front Door speaker Grill	Noise from front door trim panel while driving Video of noise before repair is performed Photos of repair