



Technical Service Bulletin

91 ConBox: DTC B1A9913: Bluetooth antenna, low energy interruption entered in addr. word 0075

91 24 91 2069361/2 April 3, 2024. Supersedes Technical Service Bulletin Group 91 number 23-68 dated February 2, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron GT, and RS e-tron GT	2023 - 2024	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Condition</i> (Fixed translation error)
1	02/02/2023	Initial publication

Workshop findings:

The following DTCs and symptom code combinations are stored in the emergency call and communications unit - J989- (address word 0075):

- **DTC B1A9913:** Bluetooth antenna, low energy Open circuit (**active/static**).

Technical Background

A software related malfunction may cause this DTC to be entered erroneously (ghost DTC).

It has no effect on the vehicle's functionality.

Production Solution

Production solution planned for MY25.

Service

No repair is available at this time.

- Do not perform any repairs. Any repairs for this concern may be denied.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.



Technical Service Bulletin

Additional Information

All parts and service references provided in this TSB (**2069361**) are subject to change and/or removal.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.