

Audi On-car analysis list from April, 4 2024

Please contact Audi Helpline before attempting repair

All topics have associated worksheets to be filled out and attached to the TAC ticket. Worksheets can be found at: [Elsa2Go](#)>>Service References>> Search v4p

	Models	MY	Engine	Trans	Topic	Topic details
	A6, A7, Q8, Q7, S4, S5	2019-2023	3.0 EA839	All	Catalytic converter	P042000: Catalyst System,Bank1 Efficiency Below •GFF Log with all fault codes and completed test plans. •VIN-4-Pin Worksheet with answers to questions •Requested pictures, see Questions/ Steps in worksheet
	Q4 e-tron	2022-2024	All	All	Charging cable cannot be removed from the vehicle	See e-tron charging questionnaire worksheet
	Q3	2021-2024	all	all	P008700 - Low fuel pressure	MIL on with DTC P008700 Low fuel pressure Fill out worksheet Delivery rate test needed
	e-tron Q and SB Q8 e-tron and SB	2019-2024	All	All	Vehicle cannot be charged, charge socket lock without function	See e-tron charging questionnaire worksheet
	Q7, Q8	2017-2019	All	All	Corrosion on wheelhouse cover plate	2017-2019 Q7 2019 Q8 Various photos and inspections, see worksheet.
	Q5	2022-2024	DMSA	all	Q5 G31 no com	U060B00 - no com to G31 Inspect harness routing Supply photos of findings in TAC case Reference worksheet for more details
	e-tron Quattro e-tron SB	2023-2024	Any	Any	Noise from Front Door Trim Panel	Noise from front door trim panel while driving Video of noise before repair is performed Photos of repair
	A6, A7, A8, etron, Q5, Q7, Q8 all variants	2021-2024	any	any	Airbag light on, DTCs B101704, B103604	Do not perform GFF test plan Do not erase DTC See TSB 2073566 See worksheet for instructions
	Q7, SQ7	2023-2024	Any	Any	Front door wind noise	Wind noise from front door while at highway speeds Details findings needed for source of noise See worksheet for further details
	A5	2023-2024	Any	Any	Noise from Front Door speaker Grill	Noise from front door trim panel while driving Video of noise before repair is performed Photos of repair