

Audi On-car analysis list from April, 12 2024**Please contact Audi Helpline before attempting repair****All topics have associated worksheets to be filled out and attached to the TAC ticket. Worksheets can be found at: [Elsa2Go](#)>>[Service References](#)>> Search v4p**

	Models	MY	Engine	Trans	Topic	Topic details
	Q4 e-tron	2022-2024	Any	Any	Charging cable cannot be removed from the vehicle	See e-tron charging questionnaire worksheet
	Q3	2021-2024	Any	Any	P008700 - Low fuel pressure	MIL on with DTC P008700 Low fuel pressure Fill out worksheet Delivery rate test needed
	e-tron Q and SB Q8 e-tron and SB	2019-2024	Any	Any	Vehicle cannot be charged, charge socket lock without function	See e-tron charging questionnaire worksheet
	Q7, Q8	2017-2019	Any	Any	Corrosion on wheelhouse cover plate	2017-2019 Q7 2019 Q8 Various photos and inspections, see worksheet.
	Q5	2022-2024	DMSA	Any	Q5 G31 no com	U060B00 - no com to G31 Inspect harness routing Supply photos of findings in TAC case Reference worksheet for more details
	A6, A7, A8, etron, Q5, Q7, Q8 all variants	2021-2024	Any	Any	Airbag light on, DTCs B101704, B103604	Do not perform GFF test plan Do not erase DTC See TSB 2073566 See worksheet for instructions
	Q5, SQ5, Q5 SB, SQ5 SB	2024	Any	Any	Q5 Airbag light	DTC B101C13, B101D13 Do not perform GFF test plan Do not erase DTC See worksheet for instructions
	Q7, SQ7	2023-2024	Any	Any	Front door wind noise	Wind noise from front door while at highway speeds Details findings needed for source of noise See worksheet for further details