



SSM 52464 2020 Escape/Corsair/Explorer/Aviator - DTC U0293 Stored In The IPC And/Or ACM

Some 2020 Escape/Corsair/Explorer/Aviator vehicles may have diagnostic trouble code (DTC) U0293 stored in the instrument panel cluster (IPC) and/or audio front control module (ACM). This DTC will not cause observable conditions or warning indicators for the customer. If this DTC is detected during pre-delivery inspection (PDI) or while diagnosing unrelated conditions, it should be disregarded.