



Technical Service Bulletin

93 Q4 drive system fault P060600/P0A1B00 Power electronics control unit 00CE (front)

93 24 48 2073435/1 April 3, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q4 e-tron	2022 - 2023	All	Not Applicable

Condition

Customer states:

- The yellow high-voltage warning lamp lights up.
- The electric drive warning lamp lights up.
- The message “Electric drive: fault. Please contact “Service” appears (Figure 1).



Figure 1. Warning message.

Workshop findings:

Intermittent/static event memory entries logged in diagnostic address 00CE (Electric drive 2):

- **P060600:** ECM/PCM Processor.
- **P0A1B00:** Drive Motor "A" Control Module.

Technical Background

Software issue in diagnostic address 00CE.

Production Solution

Optimized software implemented in electric drive control unit 2 (-JX4-, diagnostic address: 00CE).



Technical Service Bulletin

Service

This TSB replaces Pending Service Solution (PSS) TSB 2068370/1: *PSS 93 Electrical Malfunction Message Displayed on Start up, DTCs P060600 and P0A1B00 Stored in Electric drive 2.*

Please perform campaign 91EV.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (**2073435**) are subject to change and/or removal.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.